
If this resistor is missing, an error of 4013,3.10k will be reported, which is common to 6S / 7
MEIZU 16s
AI DUAL CAMERA