[Faulty model] mini4

[Fault phenomenon] The customer describes the No Power ON after the fall.



[Maintenance process] Disassemble the mini4 screen assembly. Note that the mini4's screen and cover are integrated. It is not easy to be responsible for scalding the backlight during the heating process.Remove the screen assembly and found that it has been repaired as shown:



In the picture, there are obvious signs of falling off the red circle. The circuit diagram is a backlight display backlight circuit insurance Inductor, short-circuited.



The boot normally shows the fault repair.

